





Power On/Off



Auto/off Function




Clear Testing Data



Display Light



Test Optial Power



Set Wavelength
(850,980,1300,1310,
1490,1550,1625)



Reset

Press λ and Zero Together

Calibration

1. Press λ and Light Together
The nm will disappear
2. Press Light, will increase 0.05db
Press db, will decrease 0.05db
3. Press Zero to save
4. Press λ and Light together
The nm will show again